




Air Compressor Hook Up Kit with Tubing Connection

PARTS LIST • 004-526

Use entire 50 ft. length of #050-004 Tubing.
Coil excess as shown.

Item	Part #	Description
1	050-004	Tubing 50 ft.
2	022-231	Connector (2 qty.)
3	002-379	Bushing



CONNECTION FOR
GRAVERMACH or GRAVERMAX SC

CONNECTION FOR GRAVERMAX,
GRAVERMATE or SYSTEM 3

GLENDO
CORPORATION

900 Overlander Road • Emporia, KS 66801 USA
800-835-3519 • 620-343-1084 • Fax 620-343-9640
grs@grstools.com • www.grstools.com
Last Updated: January 18, 2013